

Figure 2.1
Flow-EC Boundary Condition for San Joaquin River at Lander Ave




Figure 2.2
Flow-EC Boundary Condition for Merced River at Stevinson




Figure 2.3
Flow-EC Boundary Condition for Tuolumne River at Modesto




Figure 2.4
Monthly Pattern of Level 2 Refuge Return Flow through Mud/Salt Slough




Figure 2.5
Monthly EC of Level 2 Refuge Return Flow through Mud/Salt Slough




Figure 2.6
Monthly EC of Exchange Contractor Return Flow through Mud/Salt Slough




Figure 2.7:
Distribution of Bypass Structure Accretion computed at El Nido
given No Flow into Chowchilla Bypass at Head

